




Bridge #06662(Routine)

US 79-10 LM 8.73 over Holmes Ditch

Location: 5.3 Mi SW ArkCo-Humphrey

Team Lead: Greg Loomis **Inspection Date:** April 09, 2019

5.3 Mi SW ArkCo-Humphrey



34.39563, -91.75734



Bridge #06662(Routine)


US 79-10 LM 8.73 over Holmes Ditch

Location: 5.3 Mi SW ArkCo-Humphrey

Team Lead: Greg Loomis Inspection Date: April 09, 2019

IDENTIFICATION	
(1) State Names	Arkansas
(8) Structure Number	06662
(5) Inventory Route	79
(2) Highway Agency District	02
(3) County Code	69-Jefferson County, Arkansas
(4) Place Code	0
(6) Features Intersected	Holmes Ditch
(7) Facility Carried	US 79-10 LM 8.73
(9) Location	5.3 Mi SW ArkCo-Humphrey
(11) Mile Point	8.73 mi
(12) Base Highway Network	Yes
(13) LRS Inventory Rte & Subrte	0000079100
(16) Latitude	34.3956322940629
(17) Longitude	-91.7573350158692
(98) Border Bridge State Code	
(99) Border Bridge Structure No.	
STRUCTURE TYPE AND MATERIAL	
(43) Main Structure Type	11
Material	1-Concrete
Type	1-Slab
(44) Approach Structure Type	00
Material	0-Other
Type	0-Other
(45) No. of Spans in Main Unit	3
(46) No. of Approach Spans	0
(107) Deck Structure Type	1-Concrete Cast-in-Place
(108) Wearing Surface/Protective System	
Type of Wearing Surface	5-Epoxy Overlay
Type of Membrane	0-None
Type of Deck Protection	9-Other
AGE AND SERVICE	
(27) Year Built	1998
(106) Year Reconstructed	0
(42) Type of Service	15
On	1-Highway
Under	5-Waterway
(28) Lane	
On	2
Under	0
(29) Average Daily Traffic	3500
(30) Year of ADT	2014
(109) Truck ADT	1 %
(19) Bypass, Detour Length	40 mi
GEOMETRIC DATA	
(48) Length of Maximum Span	35 ft
(49) Structure Length	105 ft
(50) Curb or Sidewalk Width	
Left	0 ft
Right	0 ft
(51) Bridge Roadway Width Curb to Curb	40 ft
(52) Deck Width Out to Out	42.8 ft
(32) Approach Roadway Width (W/Shoulders)	36.1 ft
(33) Bridge Median	0-No median
(34) Skew	40 Deg
(35) Structure Flared	No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	41.3 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	0 ft
Ref:	
(55) Min Lat Underclear RT	99.9 ft
Ref:	
(56) Min Lat Underclear LT	0 ft
NAVIGATION DATA	
(38) Navigation Control	0-No navigation control on water
(111) Pier Protection	5-None present but re-evaluation
(39) Navigation Vertical Clearance	0 ft
(116) Vert-Lift Bridge Nav Min Vert Clear	0 ft
(40) Navigation Horizontal Clearance	0 ft

CLASSIFICATION	
(112) NBIS Bridge Length	Y
(104) Highway System	1
(26) Functional Class	2-Rural Principal Arterial - Oth
(100) Defense Highway	0-The inventory route is not a S
(101) Parallel Structure	N-No parallel structure exists.
(102) Direction of Traffic	2 - way traffic
(103) Temporary Structure	
(105) Federal Lands Highways	0-N/A
(110) Designated National Network	1-The inventory route is part of the
(20) Toll	3-On free road. The structure is toll-
(21) Maintain	1-State Highway Agency
(22) Owner	1-State Highway Agency
(37) Historical Significance	5-Bridge is not eligible for the NRHP
CONDITION	
(58) Deck	8
(59) Superstructure	8
(60) Substructure	8
(61) Channel & Channel Protection	8
(62) Culverts	N
LOAD RATING AND POSTING	
(31) Design Load	5-MS 18 / HS 20
(63) Operating Rating Method	1
(64) Operating Rating	
Type	1-Load Factor(LF)
Rating	60
(65) Inventory Rating Method	1-Load Factor(LF)
(66) Inventory Rating	
Type	3
Rating	36
(70) Bridge Posting	5-Equal to or above legal loads
(41) Structure Open/Posted/Closed	A-Open, no restriction
APPRAISAL	
(67) Structural Evaluation	8
(68) Deck Geometry	6
(69) Clearances, Vertical/Horizontal	N
(71) Waterway Adequacy	8
(72) Approach Roadway Alignment	8
(36A) Bridge Railings	1-Inspected feature meets currently a
(36B) Transitions	1-Inspected feature meets currently a
(36C) Approach Guardrail	1-Inspected feature meets currently a
(36D) Approach Guardrail Ends	1-Inspected feature meets currently a
(113) Scour Critical Bridges	5-Bridge foundations determined to be
PROPOSED IMPROVEMENTS	
(75) Type of Work	
(76) Length of Structure Improvement	0 ft
(94) Bridge Improvement Cost	\$ 0
(95) Roadway Improvement Cost	\$ 0
(96) Total Project Cost	\$ 0
(97) Year of Improvement Cost Estimate	
(114) Future ADT	4940
(115) Year of Future ADT	2028
INSPECTIONS	
(90) Inspection Date	04/2019
(91) Frequency	24 Months
(92) Critical Feature Inspection	Done Freq. (Mon) Date
A: Fracture Critical Detail	No
B: Underwater Inspection	No
C: Other Special Inspection	No

[illegible]



Bridge #06662(Routine)

US 79-10 LM 8.73 over Holmes Ditch

Location: 5.3 Mi SW ArkCo-Humphrey

Team Lead: Greg Loomis **Inspection Date:** April 09, 2019



Bridge #06662(Routine)

US 79-10 LM 8.73 over Holmes Ditch

Location: 5.3 Mi SW ArkCo-Humphrey

Team Lead: Greg Loomis **Inspection Date:** April 09, 2019

Inspection Comments

This bridge is logged from southwest to northeast.