



**Bridge #07039**(Routine, Underwater type 2)  
**US 412 -09-LM 5.52 over LOCUS CREEK RELIEF**

**Location: 2.73 MI W MO STATE LINE**

**Team Lead: James Adams Inspection Date: June 24, 2020**



Latitude:36.05243, Longitude:-90.39030


Route:412 Section:09 Log:5.52

Arnold Road ID:28x412x9xA, Arnold Log mile:5.509

District 10, Greene County

Owner: 1-State Highway Agency

2.73 MI W MO STATE LINE



36.05243, -90.39030



Bridge #07039(Routine, Underwater type 2)

US 412 -09-LM 5.52 over LOCUS CREEK RELIEF

Location: 2.73 MI W MO STATE LINE

Team Lead: James Adams Inspection Date: June 24, 2020

IDENTIFICATION	
(1) State Names	Arkansas
(8) Structure Number	07039
(5) Inventory Route	412
(2) Highway Agency District	10
(3) County Code	55-Greene County, Arkansas
(4) Place Code	0
(6) Features Intersected	LOCUS CREEK RELIEF
(7) Facility Carried	US 412 -09-LM 5.52
(9) Location	2.73 MI W MO STATE LINE
(11) Mile Point	5.52 mi
(12) Base Highway Network	Yes
(13) LRS Inventory Rte & Subrte	0000412090
(16) Latitude	36.0524304834207
(17) Longitude	-90.3903047910054
(98) Border Bridge State Code	
(99) Border Bridge Structure No.	
STRUCTURE TYPE AND MATERIAL	
(43) Main Structure Type	42
Material	4-Steel continuous
Type	2-Stringer/Multi-beam or girder
(44) Approach Structure Type	00
Material	0-Other
Type	0-Other
(45) No. of Spans in Main Unit	3
(46) No. of Approach Spans	0
(107) Deck Structure Type	1-Concrete Cast-in-Place
(108) Wearing Surface/Protective System	
Type of Wearing Surface	1-Monolithic Concrete (concurrently placed
Type of Membrane	0-None
Type of Deck Protection	1-Epoxy Coated Reinforcing
AGE AND SERVICE	
(27) Year Built	2008
(106) Year Reconstructed	0
(42) Type of Service	19
On	1-Highway
Under	9-Relief for waterway
(28) Lane	
On	4
Under	0
(29) Average Daily Traffic	8600
(30) Year of ADT	2014
(109) Truck ADT	14 %
(19) Bypass, Detour Length	4 mi
GEOMETRIC DATA	
(48) Length of Maximum Span	34 ft
(49) Structure Length	90 ft
(50) Curb or Sidewalk Width	
Left	0 ft
Right	0 ft
(51) Bridge Roadway Width Curb to Curb	75.1 ft
(52) Deck Width Out to Out	78.2 ft
(32) Approach Roadway Width (W/Shoulders)	75.1 ft
(33) Bridge Median	0-No median
(34) Skew	0 Deg
(35) Structure Flared	No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	76.1 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	0 ft
Ref:	
(55) Min Lat Underclear RT	99.9 ft
Ref:	
(56) Min Lat Underclear LT	0 ft
NAVIGATION DATA	
(38) Navigation Control	N-Not applicable, no waterway.
(111) Pier Protection	1-Navigation protection not requ
(39) Navigation Vertical Clearance	0 ft
(116) Vert-Lift Bridge Nav Min Vert Clear	0 ft
(40) Navigation Horizontal Clearance	0 ft

CLASSIFICATION	
(112) NBIS Bridge Length	Y
(104) Highway System	1
(26) Functional Class	2-Rural Principal Arterial - Oth
(100) Defense Highway	0-The inventory route is not a S
(101) Parallel Structure	N-No parallel structure exists.
(102) Direction of Traffic	2 - way traffic
(103) Temporary Structure	
(105) Federal Lands Highways	0-N/A
(110) Designated National Network	1-The inventory route is part of the
(20) Toll	3-On free road. The structure is toll-
(21) Maintain	1-State Highway Agency
(22) Owner	1-State Highway Agency
(37) Historical Significance	4-Historical significance is not dete
CONDITION	
(58) Deck	7
(59) Superstructure	8
(60) Substructure	8
(61) Channel & Channel Protection	8
(62) Culverts	N
LOAD RATING AND POSTING	
(31) Design Load	5-MS 18 / HS 20
(63) Operating Rating Method	1
(64) Operating Rating	
Type	1-Load Factor(LF)
Rating	60
(65) Inventory Rating Method	1-Load Factor(LF)
(66) Inventory Rating	
Type	3
Rating	36
(70) Bridge Posting	5-Equal to or above legal loads
(41) Structure Open/Posted/Closed	A-Open, no restriction
APPRAISAL	
(67) Structural Evaluation	8
(68) Deck Geometry	9
(69) Clearances, Vertical/Horizontal	N
(71) Waterway Adequacy	8
(72) Approach Roadway Alignment	8
(36A) Bridge Railings	1-Inspected feature meets currently a
(36B) Transitions	1-Inspected feature meets currently a
(36C) Approach Guardrail	1-Inspected feature meets currently a
(36D) Approach Guardrail Ends	1-Inspected feature meets currently a
(113) Scour Critical Bridges	5-Bridge foundations determined to be
PROPOSED IMPROVEMENTS	
(75) Type of Work	
(76) Length of Structure Improvement	0 ft
(94) Bridge Improvement Cost	\$ 0
(95) Roadway Improvement Cost	\$ 0
(96) Total Project Cost	\$ 0
(97) Year of Improvement Cost Estimate	
(114) Future ADT	10307
(115) Year of Future ADT	2025

INSPECTIONS *			
(90) Inspection Date			06/2020
(91) Frequency			24 Months
(92) Critical Feature Inspection	Done	Freq. (Mon)	Date
A: Fracture Critical Detail	No		
B: Underwater Inspection	No		
C: Other Special Inspection	No		
* The inspection date and frequency information in this box contains the current NBI date and frequency information. Please refer to the report header for the date this inspection was conducted.			



Bridge #07039(Routine, Underwater type 2)

US 412 -09-LM 5.52 over LOCUS CREEK RELIEF

Location: 2.73 MI W MO STATE LINE

Team Lead: James Adams, Inspection Date: June 24, 2020

ELEM	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
12	Reinforced Concrete Deck	SF	7113	6367	252	494	0
1120	Efflorescence/Rust Staining	SF	111	0	12	99	0
1130	Cracking (RC and Other)	SF	635	0	240	395	0
107	Steel Open Girder/Beam	LF	810	810	0	0	0
515	Steel Protective Coating	SF	6749	6749	0	0	0
215	Reinforced Concrete Abutment	LF	156	149	0	7	0
1120	Efflorescence/Rust Staining	LF	7	0	0	7	0
225	Steel Pile	EA	18	18	0	0	0
515	Steel Protective Coating	SF	980	980	0	0	0
234	Reinforced Concrete Pier Cap	LF	154	148	6	0	0
1120	Efflorescence/Rust Staining	LF	3	0	3	0	0
1130	Cracking (RC and Other)	LF	3	0	3	0	0
310	Elastomeric Bearing	EA	18	18	0	0	0
321	Reinforced Concrete Approach Slab	SF	4307	3883	228	196	0
1080	Delamination/Spall/Patched Area	SF	2	0	0	2	0
1130	Cracking (RC and Other)	SF	422	0	228	194	0
331	Reinforced Concrete Bridge Railing	LF	182	163	19	0	0
1080	Delamination/Spall/Patched Area	LF	2	0	2	0	0
1120	Efflorescence/Rust Staining	LF	3	0	3	0	0
1130	Cracking (RC and Other)	LF	14	0	14	0	0





**Bridge #07039**(Routine, Underwater type 2)

**US 412 -09-LM 5.52 over LOCUS CREEK RELIEF**

**Location: 2.73 MI W MO STATE LINE**

**Team Lead:** James Adams **Inspection Date:** June 24, 2020



**Bridge #07039**(Routine, Underwater type 2)

**US 412 -09-LM 5.52 over LOCUS CREEK RELIEF**

**Location: 2.73 MI W MO STATE LINE**

**Team Lead:** James Adams **Inspection Date:** June 24, 2020

## Maintenance Needs

**Date Reported:** 07/02/2018  
**Priority:** C - Important  
**Type of Work:** None  
**Status:** Monitor  
**Component:**

---

## Deficiency Description

Deck has several unsealed transverse and longitudinal cracks & diagonal cracks at both corners of span 1 over bent 1 & left corner of span 3 at bent 4.

## Remarks

---



**Bridge #07039**(Routine, Underwater type 2)  
**US 412 -09-LM 5.52 over LOCUS CREEK RELIEF**  
**Location: 2.73 MI W MO STATE LINE**

**Team Lead:** James Adams **Inspection Date:** June 24, 2020

**Date Reported:** 06/24/2020  
**Priority:** C - Important  
**Type of Work:** Repair  
**Status:** Open  
**Component:** Deck

---

**Deficiency Description**

Approach slabs have several unsealed cracks.

**Remarks**

---



**Bridge #07039**(Routine, Underwater type 2)

**US 412 -09-LM 5.52 over LOCUS CREEK RELIEF**

**Location: 2.73 MI W MO STATE LINE**

**Team Lead:** James Adams **Inspection Date:** June 24, 2020

## Inspection Comments

-

---

### Deck Notes

Approach slabs have several unsealed cracks.

Bridge rails have several vertical cracks, some with efflorescence.

Deck has several unsealed transverse and longitudinal cracks & diagonal cracks at both corners of span 1 over bent 1 & left corner of span 3 at bent 4.

Soffit at Bay 4 does not have any SIP forms. Exposed soffit has several transverse cracks with efflorescence.

---

### Superstructure Notes

Weathering steel superstructure is light brown in color with a light granular texture.

---

### Substructure Notes

Caps have a few minor cracks.

Backwall portion of concrete caps have a few vertical cracks with efflorescence.

Underwater type 2 inspection performed this report.