



Deck Truss (6)

- * In-Service NR Deck Truss (3)
- ⊙ Demolished NR and RP Deck Truss (4)
- ▣ Preserved Deck Truss (0)
- ⊕ Reserve Pool Deck Truss (0)
- Evaluation Deck Truss (3)



Evaluation Deck Truss Properties	
General Attributes	
Name	Value
Bridge_Number	01486
Type	409
HAER_Number	
county_name	Van Buren
District	8
Route	65
Section	08
Date_Built	1931
SHPO_Number	
Log_Mile	1.14
Photo1	\\sql2\gis\Environmental\HB Photos\01486\01486.pdf
Name	
Description	Deck Truss
Topographic_Map	Clinton
Programmed	No
HB_Inventory_Date	
Water_Crossing	South Fork Little Red River
Demolished	No
In_Service	Yes
HAER	
Nat_Reg_Form	
Pool_Reserve	No
HB_Demolish	
Marketing_Letter	
FHWA_4f	
SHPO_MOA	
Evaluation	True
Unique_Attributes	cantilevered
Spans	3
Main_Span_Length	100
Main_Span_Width	35.5
Vertical	
Total_Length	405
Photographed	True
Field_Condition	good

EVALUATION BRIDGE #01486
US HIGHWAY 65
VAN BUREN COUNTY
DECK TRUSS
CONDITION – GOOD
BUILDER – M. K. ORR, LITTLE ROCK, AR



Evaluation Bridges Properties	
General	Attributes
Name	Value
Bridge_Number	02597
Type	309
HAER_Number	
county_name	Carroll
District	9
Route	62
Section	03
Date_Built	1952
SHPO_Number	
Log_Mile	4.30
Photo1	\\sql2\gis\Environmental\HB_Photos\02597\02597.pdf
Name	
Description	Deck Truss
Topographic_Map	Beaver
Programmed	No
HB_Inventory_Date	
Water_Crossing	White River
Demolished	No
In_Service	Yes
HAER	
Nat_Reg_Form	
Pool_Reserve	No
HB_Demolish	
Marketing_Letter	
FHWA_4f	
SHPO_MDA	
Evaluation	True
Unique_Attributes	
Spans	5
Main_Span_Length	128
Main_Span_Width	30.6
Vertical	
Total_Length	787
Photographed	True
Field_Condition	excellent

EVALUATION BRIDGE #02597
US HIGHWAY 62
CARROLL COUNTY
DECK TRUSS
CONDITION – EXCELLENT
BUILDER – FORCUM JAMES COMPANY, DYERSBURG, TN



Evaluation Deck Truss Properties	
General Attributes	
Name	Value
Bridge_Number	11621
Type	409
HAER_Number	
county_name	Columbia
District	7
Route	61
Section	C
Date_Built	1955
SHPO_Number	
Log_Mile	3.29
Photo1	\\sql2\gis\Environmental\HB Photos\11621\11621.pdf
Name	
Description	Deck Truss
Topographic_Map	Village
Programmed	No
HB_Inventory_Date	2005
Water_Crossing	Sloan Creek
Demolished	No
In_Service	Yes
HAER	
Nat_Reg_Form	
Pool_Reserve	No
HB_Demolish	
Marketing_Letter	
FHWA_4f	
SHPO_MOA	
Evaluation	True
Unique_Attributes	Pratt deck truss
Spans	2
Main_Span_Length	24
Main_Span_Width	21.6
Vertical	
Total_Length	48
Photographed	True
Field_Condition	good

EVALUATION BRIDGE #11621
COUNTY ROAD 61
COLUMBIA COUNTY
DESK TRUSS
CONDITION – GOOD
BUILDER - UNKNOWN